

Release Notes

Model: HS-3200 Firmware Release Info

Dec. 06, 2018

Firmware Versions

- Image_ImEx v0.03 (Windows version)

File name: HS3200_Image_ImEx_v0.0.3

Issues

1. This software allows users to import images into the HS-3200 or to export images from the HS-3200. Please unzip the zip file "HS3200_Image_ImEx_v0.0.3" into a folder of a Windows PC (Windows XP or above). After the zip file is unzipped, please double click the "**SwitcherImageImEx_v0.0.3.exe**" to start the installation.

Oct. 19, 2018

- USB V0961+ K/B v1.6.6

File name: HS-3200 firmware update usb_v0961_kb166

Issues

1. Improved Ethernet connection compatibility issue. The OSD setup menu can support Static IP/DHCP switching and network def.
2. Solved the issue that when DVE transition is executed, the dark black will become brighter.
3. When running Factory Default, the SDI out will return to the "PGM" output which is the default value and the Keyer will return to Key 1 position
4. Improved the Auto Chromakey no response issue and the Auto Chromakey can be used when the source is Flex Src.
5. The Key/Fill Source function is added for the Flex Src.
6. Fixed the issue that When Audio source= External, the abnormal jumping problem will occur for the MV Audio Indicator.
7. Solved the asymmetry issue for the left side/right side of the Flex PIP X position.
8. Added the function that the version No. will be displayed on the PVM row once the Menu button of the keyboard is pressed during the power On LED scanning.
9. When the FS button on the keyboard is pressed, the keyboard will light up in blue. If the brightness=5 is set, it will achieve maximum brightness for improving the outdoor recognition. (SE-3200 CTL needs to use 10V/2A adaptor).
11. Improved the HDMI in EDID compatibility with KMU-100 or Notebook PC and then video can be displayed properly.

Sept 19, 2018

Firmware Versions

- S/W v0.9.5.3
- K/B v1.6.1

File name: HS-3200 firmware update v0.9.5.3 + kb v1.6.1

Issues

1. Improved the stability issue in system booting.
 2. Improved the HDMI input/output compatibility issue.
 3. Improved the distortion issue of the SDI audio input.
 4. Improved the issues that the keyboard firmware will be updated abnormally in booting and the version No. will be shown in Ver. 0.0
 5. Improved the stability issue for switching resolutions. Moreover, the desired resolution can be selected directly from the dialogue box.
 6. The SE-3200 Controller v0.9.5.3.exe is the PC App for importing Still/Clip/Logo/Ani Logo only. This SE-3200 Controller v0.9.5.3.exe file is for the SE-3200 & HS-3200 only, for other switchers, please do not use this file. It is recommended to use this PC app by keyboard. The SwitcherImageEx software for the SE-3200 will be provided in the near future for replacing this file.
 7. The resolution for 1080i was improved. However, if the object is moved or the object is used for PIP function, it is possible to see the sawtooth edge. It is recommended to use the 1080p resolution.
-