

## Release Notes

---

### Model: RMC-180 MARK II

---

**Jun. 27, 2022**

RMC-180 MARK II Firmware

- Version: FW1.150
- File Name: RMC-180 MARK II FW Update\_V1.150

#### Issues

1. After the operation for the FN14 GROUP PLAY and FN15 PTR10 ADJ. are finished, the time for the timeout will be extended by 10 seconds.
  2. The word strings for the "FN14 GROUP->8. PRESET POSITION->FOCUS MODE, IRIS MODE" are adjusted to be consistent with the PTR-10.
  3. The "FN15 PTR10 ADJ-> 2. P/T SPEED is changed to "2X SPORT, AUTO and NORMAL modes" according to the PTR-10 firmware v1.57.
  4. The display value for the "FN15 PTR10 ADJ->4. PAN OFFSET ADJ & 8. TILT OFFSET ADJ" are adjusted to be consistent with the PTR-10.
  5. The word strings for the "FN15 PTR-10 ADJ->21 REMOTE-OUT MODE" are adjusted to be consistent with the PTR-10.
  6. The "20. TALLY LIGHT" is modified to "29. TALLY LIGHT".
- 

**Mar. 14, 2022**

RMC-180 MARK II Firmware

- Version: FW1.13
- File Name: RMC-180 MARK II FW Update\_V1.13

#### Issues

1. Fixed the disconnection & reconnection and abnormal LCD display issues when the RMC-180 MARK II is connecting with the PTC-300/PTC-280 and the WB One Push mode and video format are adjusted.
  2. Fixed the video format from 1080/29.94p to 1080/29.97p when the RMC-180 MARK II is connecting to the PTC-140.
- 

**Feb. 18, 2022**

RMC-180 MARK II Firmware

- Version: FW1.12
- File Name: RMC-180 MARK II FW Update\_V1.12

#### Issues

1. Fixed the issue of the abnormal connection which is happened when setting the VISCA

---

address 82 to 87. In the version v1.11.

2. Added group play 1-8 on FN16 (PTR-10 FN14).
3. Fixed the abnormal issues for the controlling and LCD displaying when the RMC-180 MARK II is connected to the PTR-10 and PTC series cameras simultaneously. In this situation, it will cause an LCD menu timeout issue, which is the root cause of the above-mentioned issues.
4. When the PTR-10 is connected to the RMC-180 MARK II, the FPGA & MOTOR information will be removed in cam info. It will be changed to MCTL.
5. Added the auto-detection function for detecting the status when the camera connection is lost or the camera is reconnecting to the RMC-180 MARK II.
6. Solved the wrong LED indicator issue when using the STORE plus Channel Preset buttons.

---

### **Sept. 8, 2021**

#### **RMC-180 MARK II Firmware**

- Version: FW1.09
- File Name: RMC-180 MARK II FW Update\_V1.09

#### **Issues**

1. When the RMC-180 MARK II is operated in Advance Mode, and the "STR" button is pressed, the color of the buttons for "CH A", "CH B", "CH C" and "CH D" will be lit in red rather than yellow.
-