Release Notes

Model: BC-50

Aug. 17, 2021 Main Board Unit

Firmware (MB CPU)

Version: V7.2.62

File name: J2600_P3.D_V7.2.62_24M_20210517

Issues

1. The B & W on/off command is imported.

2. The SRT Listener function is supported.

3. The Auto-Focus function is improved.

Apr. 15, 2020   Main Board Unit

Firmware (MB CPU)

Version: V7.2.58

File name: J2600_P3.D_V7.2.58_24M_20200324

Issues

1. Web control UI cancels Flash and adds support for HTML5.

2. Optimize browser stability.

3. Optimize firmware upgrade procedure.

4. Change the text "RTMP" to "RTMP(S)".

5. Improve the issue that the resolution will be interrupted when streaming the RTMPS video at 1080P 50/60. Note: However, at present, there will still be a situation of dropping.

6. Fix the issue that when the SDI is set to 1080p60, if the RTMPS or the multicast is enabled, it will cause abnormal playback for the RTMPS. Moreover, the issue that the HTML5 can not play video is also fixed.

Jan 18, 2018   Main Board Unit

Firmware (MB CPU)

Version: V7.2.39

File name: J2600_P3.D_V7.2.39_24M_20171227.img

Issues

1. Add image's B&W modes

2. Add Guard Position, i.e. Preset 0 Priority function in the SETTING

3. Add DVIP function

Sep 29, 2017   Main Board Unit

Firmware (MB CPU)

Version: V7.2.31

File name: J2600_P3.D_V7.2.31_25M_20170914.img

Issues

1. Added the ZOOM IN/OUT of the PELCO-P Protocol command
2. Added and fixed some of the VISCA Protocol commands

Jul 19, 2017   Main Board Unit

Firmware (MB CPU)

Version: V7.2.24

File name: J2600_P3.D_V7.2.24_24M_20170707.img

Issues

1. Fixed the issue of non-obvious change after iris or exposure adjustment
2. Lens type 2 fix
3. Removed SDK/Multicast function
4. Browser page now includes Datavideo logo
5. Added traditional Chinese OSD menu