Release Notes

Model: ITC-300 & ITC-300SL

Sept. 2, 2019

ITC-300 & ITC-300SL Firmware

- Version: ITC-300_V3K & ITC-300SL_V3h
- File name: ITC-300_V3K & ITC-300SL V3h firmware update

Issues

1. Fixed the issue that the RCA Audio in cam will mix with the voice.

2. Fixed the issue that when the ALL or HOLD key is pressed, there are sometimes 1 or 2 keys will light later than others.

3. Fixed the issue that when users go into PP mode by "Press ALL->Press "Shift"+ "Hold", the ITC-300 will crash.

4. Fixed the issue that the Tally lights (the Red/the Green) can light at the same time.

5. Fixed the issue that even the Audio IN function is not turned on, users can hear the RCA IN sound from the beltpack.